# Scala Animal Thermometer SC 1091





Instructions for use

After the measurement is completed, the temperature value measured remains in the display until the SC 1091 is switched off. To turn the device off after use, press the 0/II button briefly. The signal tone will again be sounded. If the device is not switched off, a signal tone is sounded after around 3 minutes and the device then switches off automatically.

# Function test

The thermometer is checked for correct functioning automatically every time it is switched on. All segments are displayed, and then L°C. If a failure (measurement inaccuracy) is recognised, "ERR" (Error) is shown in the display.

# Display of last measured value

If you keep the 0/I button pressed for longer than three seconds, the last measured value will be shown in the display. As soon as you release the 0/I button, the device is ready to take measurements.

# Cleaning and disinfection

The veterinary thermometer is watertight.

# Please note that watertight does not mean that the thermometer is also tight in aggressive disinfection or solvent solutions!

The thermometer can be cleaned by wiping with any of the disinfection tissues listed below or with a moist cloth containing any of the following disinfection agents.

Disinfectant	Supplier	Use
Kodan <sup>®</sup> tissues	Schülke & Mayr	
EuroSept <sup>®</sup> Max	Henry Schein Inc.	According to supplier
Wipes		instructions for plastic
Medizid Rapid	Rösner-Maut by Meditrade	surfaces
	GmbH	
Helipur <sup>®</sup> H plus N	B. Braun Melsungen	

# Changing the battery

As soon as the  $\bigcirc$  symbol appears in the display, the battery has run out and requires replacement. Always replace the discharged battery with one of the same type. To do this, proceed as follows:

Pull the cover off the battery compartment. The battery can now be accessed. Remove the used battery with the help of a pointed object (pincers, small screwdriver etc.) and put the new battery (LR 41 or SR41) in. Please make sure it is the right way round.

# Guarantee

We give a guarantee period of 2 years from the date of purchase. We


# Special features

The SC 1091 is a maximum thermometer, i.e. the highest temperature is displayed latest after 25 seconds. The most recent measured value is always saved.


# Safety information

- The SC 1091 is suitable only for measuring animal body temperatures.
  The thermometer contains small parts (batteries, etc) which could be
- swallowed by small children. Please keep the thermometer and its batteries out of the reach of small children.
- Protect the SC 1091 from direct sunshine and temperatures above 50°C.
- Never drop the SC 1091 or open it (with the exception of the battery compartment for battery replacement).

# **Operating manual**



Press the 0/I button to switch on. A short signal tone shows that the device is in the "switched on" condition. A segment test takes place simultaneously (checks all display segments and carries out an internal function test (see under "Function test")).



After this, if the temperature measured by the temperature sensor is less than 32°C, the display shows an "L" and "°C". After around one second, the "°C" starts to blink. The "L" stands for low (less than 32°C). The current temperature is continuously displayed during measurement, and the "°C" blinks during the entire measurement time. The measurement is completed after around 25 seconds.

- 2 -

guarantee perfect design of this article. We will rectify all material or manufacturing errors during the guarantee period. The guarantee excludes damages caused by improper handling, related to the battery or to the packaging.

# Specifications

opecifications	
Туре:	maximum thermometer
Measuring range:	32.0°C to 43.9°C
	Temperature below 32.0°C: display "L" for low.
	Temperature above 43.9°C: display "H" for high.
Measurement accuracy	
Self-test:	Automatic internal check of test value $37.0^{\circ}$ C. In case of deviation > 0.1°C, "Err" will be displayed.
Display:	3-digit liquid-crystal (LCD display).
Battery type:	1 no.: LR 41 or SR 41.
Battery display:	The $\mathbf{\nabla}$ shows when the battery is discharged.
Storage temperature:	0°C to 50°C

# Disposal note



Defect devices or devices which are taken out of operation at the end of their service life may still contain residues which could present a risk to the environment. Please dispose of the device in a suitable and correct way at a collection point for old electrical items.

Batteries must be disposed of correctly. There are containers for battery disposal at battery dealers and in communal collection points.

# Explanation of symbols

•	•	
-	Manufacturer	
CE	Complies with EU directives	
*	Product type BF	
OXX	Disposal notes	
[]i	Read the instruction manual	
	Production period (month/year)	
RoHS	Compliant with EU directive 2002/95/EG	

Scala Electronic GmbH Ruhlsdorfer Straße 95 14532 Stahnsdorf www.scala-electronic.com